


# HIGH TEMPERATURE CALORIMETRY

#### DIFFERENTIAL SCANNING CALORIMETRY

Differential Scanning Calorimetry (DSC) is the most popular thermal analysis technique for

- research and development
- quality management
- failure analysis, and
- process optimization

It measures endothermic and exothermic transitions as a function of temperature. Transitions measuremend include Tg, melting, crystallization, curing and cure kinetics, onset of oxidation and heat capacity.



## TECHNICAL SPECIFICATION

LINSEIS High Temperature DSC HDSC PT1600

Temperature range

Heating and cooling rates

Temperature accuracy

Resolution

Atmospheres

Vacuum

Crucibles

RT up to 1400 °C 0,1 up to 50 °C/min

+/-0,5 °C

 $0.3 \mu W$ 

inert

10<sup>-2</sup> Pa

Al<sub>2</sub>O<sub>3</sub> 0,12 ml, Platinum 0,12 ml

## MEASUREMENT PRINCIPLE

The temperature of the sample unit, formed by sample and reference material, is varied in a specific program and the temperture difference between the sample and the reference material is measured as a function of temperature.

## APPLICATION EXAMPLES

- Enthalpy, melting energy
- Specific heat
- Glass point
- Thermal stability
- Oxidation stability
- Purity
- Phase transformation temperature
- Solidus/Liquidus relationship
- Eutecticum
- Polymorph transformations





